Industrial Engineering

with which is consolidated

Industry Illustrated

Volume 85

January to December, 1927

McGRAW-HILL PUBLISHING COMPANY, INC.
10th Avenue and 36th Street
NEW YORK

INDUSTRIAL ENGINEERING

INDEX TO VOLUME 85

January to December, 1927

GENERAL INDEX

PAGES BY MONTHS

January	1 to 44
February	45 to 100
March	101 to 148
April	149 to 196
May	197 to 244
June	245 to 300
July	301 to 348
August	349 to 396
September	397 to 444
October	445 to 500
November	501 to 548
December	549 to 600

A

Accident prevention (see Safety).
Acetylene, oxy- (see under Welding).
Advertising, industrial equipment (Practical Pete), 225.
Air compressors (see Compressors).
Alarms (see Signals).
Alternator required for industrial plant, size of (Frederick Krug), 232.
Ammeters (see under Meters).
Arc-rupturing devices (H. D. James), *411
Arc welding (see Welding).
Armatures (see under Motor reconnection and repair).
Association of Iron and Steel Electrical Engineers:
——Convention (Practical Pete), 285.
——Convention, report of, *317, editorial comment, 331.

B

Babbitt (see under Bearings).
Bakelite shown in exhibit, industrial uses of, 244.
Batteries, storage:
——Charging:
Automatic, station for trucks (D. F. O'Donnell), *235.
Exciter, from (C. Otto von Dannenberg), (V. E. Johnson), (J. F. Morgan), (Horace Turville), (E. J. Elvish), *535.
——Operation and care of, 233.
Bearings:
——Anti-friction:
Flour mill, in (J. Hanson), 37.
Installing, in sleeve-bearing motors (O. C. Callow), 432.
Motors, and sleeve-type on (J. S. Murray), 388.
Rolling mills, on roll necks of (E. C. Gainsborg), 324.
——Attention to, may prevent a fire in your plant, proper (editorial comment), 84.
——Babbitting:
Bearing seats for bull or roller, in (Donald A. Hampson), *436.
White metal in rebabbitting, using (W. E. Warner), 540.
——Ball:
Grinding machine, use of, on heavy (G. R. Hanks), 237.
Lubricating (E. J. Morrissey), 34, (Nathaniel W. Blanchard), (H. W. Holdsworth), (W. E. Warner), 136.
——Care of, in emergency prevented breakdown, familiarity with (Donald A. Hampson), 294.
——Clean, seldom are out of repair (editorial comment), 532.
——Hauger, installing ball or roller (Donald A. Hampson), 237.
——Improperly bored, causes trouble (Donald A. Hampson), 93.
——Life of, increased by individual fit (G. H. Emerson), 542.
——Motor, problem, an analysis of the (Frank W. Cramer), 323, comment (J. S. Murray), 388.
——Oil grooves in bronze and babbitt (Grady H. Emerson), (H. D. Fisher), (H. J. Achee), (W. E. Warner), *429.
——Oil well cover permits easy access to (Charles A. Peterson), *144.
——Oilless, on loose-pulley drives (Donald A. Hampson), 37.
——Overheating of, magnetized shaft of motor and (Charles Reichenbach), (E. J. Morrissey), (W. E. Warner), 339.
——Relining, using oxyacetylene torch when, 189.
——Roller:
Conveyors, application of, to (S. M. Weckstein), *575.
Lubricating (E. J. Morrissey), 34, (Nathaniel W. Blanchard), (H. W. Holdsworth), (W. E. Warner), 136.
Tapered, on roll necks (Fred Waldorf), *321.
Bearings (Continued):
——Rolling mills, for use in (C. J. Klein), 322.
——Troubles—how they have been solved, *481.
Belts (see also Motor drive).
——Abuse of, on high-inertia loads (W. B. Neeper), 456.
——Breaks, protecting heater units when blower (D. W. Haire), *295.
——Center distances for leather belt drives, proper (Roy C. Moore), *201.
——Dressings, applying, 436.
——Dust on, decreasing pulley wear from abrasive, 295.
——Engines a belt to its task (editorial comment), 491.
——Horizontal quarter-turn, drives (R. F. Jones), *155.
——Idlers:
Fixed and flexible, on leather (Roy C. Moore), *310.
Two, used to increase arc of contact (J. Edgar Rhoads), *456.
——Lay out drives by guess, do not (editorial comment), 331.
——Leather, replacing (Claude O. Streeter), 57.
——Motor drives, use of, on (Gordon Fox), *101.
——Overloaded, how many of your, are (editorial comment), 533.
——Pulley:
Diameter on power transmitted by leather, influence of (Roy C. Moore), *357.
Narrow, special belts are solving the problem of the (editorial comment), 287.
——Rubber:
Replacing (E. J. Black), 57.
Transmission, using (C. F. Conner), *12.
——Short-center drives:
Motor troubles with (editorial comment), 377.
Prevents pulley wear due to slip of dusty, *595.
——Size required for certain drive (E. I. Pease), (Grady H. Emerson), (R. R. Tatnall), (Charles Hathaway), (Archie L. Forger), 31.
——Slippage on coal breaker drive, eliminating (D. W. Pedrick), 480.
——Speed:
And power—their relation in leather (Roy C. Moore), *509.
Determining, chart for, *294.
Blow torch, care of (C. A. P.) *439.
Blowers:
——Belt breaks, leather units protected when (D. W. Haire), *295.
——Driven, how should this, be (J. T. Alford), (H. D. Fisher), (F. C. Wood), (Percy Lamothe), (E. J. Morrissey), 333.
Bolts, bushings method of lengthening anchor (R. M. Thomas), *543.
Books, practical:
——Iron and steel, non-technical chats on (La Verne W. Spring), 443.
——Repair shop diagrams and connecting tables for induction motors (Daniel H. Braymer and A. C. Roe), 443.
——Switching equipment for power control (Stephen Q. Hayes), 443.
——Underground systems for electric light and power (T. C. Ruhling), 443.
——Wiring for electric light and power, standard (H. C. Cushing, Jr.), 443.
Brick, preventing formation of white incrustation on (Irving Kass), (H. D. Fisher), (Nathaniel W. Blanchard), 494.
Brushes (see Motor reconnection and repair).
Bus structures, layout of heavy (W. H. Boyce), *256.
Buildings (see Plant, the).
Business: long-time guarantees of prosperity (Edward J. Mehren), *523.
Buying according to specifications can be overdone (editorial comment), 580.

C

Cables (see also Wire):
——Clamp, emergency use of oversized (G. A. Luers), 410.
——Elevator, checking condition of (J. M. Walsh), 493.
——Overheating:
Importance of skin effect in (B. W. Scott), 292.
Trouble from (C. Otto von Dannenberg), (E. J. Morrissey), (Lee F. Dann), 136.
——Socketing wire, *511.
——Wiring for motor installations (Gordon Fox), *360.
Cement mills (See Mills).
Chain drive (see also Motor drive):
——Calendar drive trouble traced to eccentric gear, *460.
——High-speed, developments in, 190.
——Limitations of, that affect the design and service for many transmission purposes (A. B. Wray), *589.
——Long-center, substituted for level gears and shaft (Earl C. Moss), *343.
Chain drives (Continued):
——Motor drives through wormspeed reducers, and variable-speed transmission (Gordon Fox), *209.
——Roller:
Quarter-turn drive, used on (Donald A. Hampson), 540.
Saw trimmer drive, for, *295.
——Silent, on surface grinder (Donald A. Hampson), *437.
Charts (see Records).
Chicago Union Station, trucks and tractors at (W. Landess), *63.
Circuit breakers:
——Setting, trouble in (E. J. Morrissey), (E. J. Elvish), (Frank C. Ammann), *492.
Coal (see Handling materials).
Coils (see under Motor reconnection and repair).
Coke plant, improving operation of byproducts (A. L. Bingham), *69.
Communication (see Signals).
Commutators (see under Motor reconnection and repair).
Compass, wooden case for protecting a pocket (Charles A. Peterson), 543.
Compensators (see under Motor control).
Conductors (see Cables and Wire):
Conduit (see also Wiring):
——Flexible, making end connection for (Charles A. Peterson), *240.
——Grouping of wires in, for two-phase system (H. S. Ramsay), (C. Otto von Dannenberg), (Ernest Dickinson), (A. C. Barker), (D. W. Blakeslee), (Alex Brenner, Jr.), *88.
——Wiring, locating trouble in (Albert J. Friess), (Nathaniel W. Blanchard), (John J. Lynch), *338.
Construction changes under difficulties (Practical Pete), *129.
Contactor coils reduced by using reactors, effect of overvoltage on (E. J. Morrissey), 35.
Control, motor (see Motor control).
Controllers (see Motor control).
Converters:
——Rotary, collector rings, replacing worn (Philip N. Enigh), 144.
——Rotary, trouble due to poor contacts (Nicholas J. Weiss), 39.
Conveyors:
——Bearings to, application of roller (S. M. Weckstein), *575.
——Complex system of magnetically controlled (P. T. Van Bibber), *507.
——Control to stop motor when, clogs (Charles A. Peterson), *234.
——Floor to floor (Edward J. Tournier), *517.
Cords (See Wire).
Costs:
——Daylight illumination in industrial plants (M. Luckiesh and R. E. Mausk), *307.
——Lighting systems, cutting (O. C. Callow), *66, comment (G. R. Kilbourn), 174, Answer by author, 175.
——Maintenance costs, how we control our (Thomas W. Suddard), *45.
——Power transmission, helping to cut (editorial comment), 490.
——Production delays reduced by eliminating motor trouble (J. Elmer Housley), 71.
——Production, let your lighting system help to cut (editorial comment), 427.
——Water heating, lowered by electric heater, 538.
Cranes (see also Handling materials and Hoists):
——A.c. and d.c. motors for, comparative advantages of (R. F. Emerson), *315.
——Collector bars, substitute for (C. E. Schirmer), (R. P. Diehl), (D. W. Blakeslee), *34.
——Lubrication and inspection of, routine for (D. W. Blakeslee), 238.
——Monorail, supporting trolley wire for (Nathaniel W. Blanchard), *235.
——Operators, safety rules for the guidance of, 424.
——Overhead, elimination of hazards in the operation of (C. E. Sankey), *283.
Cutting (see under Welding).

D

Diagrams (see Records).
Distribution:
——D.c. to a.c. service, changing a system (Thomas C. Hayes), *149.
——Disadvantage of supplying several departments from one feeder (Grady H. Emerson), 341.
——Planning an installation of electrical equipment (Marin Phillips), *1, comment (Charles A. Peterson), 188.
——Power, in a large machine shop (Frank E. Gooding and C. E. Brown), *520.
——Steel mills, in (Arthur J. Whitcomb), *255.
——Three-phase, four-wire system, advantages of (C. Otto von Dannenberg), (Horace Turville), (John W. Bantau), (C. W. Roselle), (E. J. Elvish), *378.
Drills, electric:
——Maintenance and repair work, in (Edwin L. Connell), *160

*Indicates illustrated article.

En 620.5
f In 206

Drills, electric (Continued):
——Speed of, changing (T. M. Peterson), (H. S. Ramsay), 431.
Dust explosions, factors that influence origin and extent of, 19.

E

Edison Electric Applicance Company's plant, material handling in (D. B. Kift), *397.
Editorial comments, 28, 83, 84, 130, 178, 226, 286, 330, 376, 426, 490, 532, 580.
Education must supplement safeguards (editorial comment), 331.
Electromagnet (see Magnet).
Elevator:
——Cables, checking condition of (J. M. Walsh), 493.
——Chain, recast factory methods (Edward J. Tournier), *558.
Employee relations (see Job, the).
Equipment (see New equipment).
Exciter:
——Generator overload relieved by idle (H. G. Millican), 538.
——What is wrong with this? (Grady H. Emerson), (Claude D. Martin), (E. J. Morrissey), (Gordon S. Mayhew), (J. V. Miller), 184.

F

Factor, power (see Power factor).
Fans:
——Auxiliary, keeps overloaded motor cool, *340.
——Drive solves operating problem, flexible, *93.
——Exhaust, method of driving (E. Ogur), *142.
——Motor, heating of (Frank Harle), 231.
——Static should be accurately determined, why (editorial comment), 287.
Feeders without interruption to production damaged (Leo E. Beneze), 235.
Filing (see Records).
Fire (see also Safety):
——Bearings may prevent a, in your plant, proper attention to (editorial comment), 84.
——Protection, every employee shares responsibility for (editorial comment), 427.
——Protection for an industrial plant, providing (Al Anselm), *405.
——Stewart-Warner Speedometer Corporation's supervision over fire and watch service (J. A. Kaupel), 569.
Fixtures (see Lighting).
Flood means to the plant engineer, what a (G. A. Van Brunt), *551, editorial comment, 580.
Floodlighting (see Lighting).
Food industry, power in the (Joseph J. Merrill), 123.
Freight oversights that cost money (Practical Pete), 375.
Furnace, electric (see Heating).
Fuses:
——Blowing of, on transformer bank (H. J. Achee), (C. Otto von Dannenberg) *494.
——Blowing on transformers, cause of (C. Otto von Dannenberg), 90, (H. S. Ramsay), (W. E. Warner), (A. C. Barker), 184.
——Panel board, locating blown ones on (James P. Marshall), *92.
——Puller, inexpensive and durable (Charles A. Peterson), *293.
——Testing, to prevent motors running single-phase (H. J. Achee), (Harold H. Steele), (E. J. Morrissey), *133.
Fynn-Weichsel motor (see under Motors).

G

Gage for determining depth of water in wells, portable (Charles A. Peterson), *435.
Gary, Elbert H., death of (editorial comment), 426.
Gears (see also Pinions):
——Application of, and speed reducers on motor drives (Gordon Fox), *162, comment (T. C. Roantree), 388.
——Eccentric, trouble with calender drive traced to, *460.
——Noisy, quieting (Donald A. Hampson), 143.
——Shearing pin, substitute for (L. E. Dunham), (Garson A. Reese), 290.
——Standards for industrial, are now in sight (editorial comment), 376.
——Worm reduction units (G. H. Acker), *6.
Generators:
——Altitude on capacity of, effect of (R. F. Emerson), (W. E. Warner), (Martin G. Lane), *337.
——Armatures, rewinding small headlight (Carl A. Wagner), 344.
——Charging, trouble with storage battery (H. J. Achee), 136.
——Coils:
Field, emergency repair of defective (Charles A. Peterson), 439.
Grounded, locating, in a.c. (H. J. Achee), 292.
——Interpoles, polarity of (C. Otto von Dannenberg), (Henry Scherl), *432.
——Overload relieved by idle exciter, (H. G. Millican), 538.
——Parallel, operating, in (H. J. Achee), (Horace Turville), (Frederick Krug), *229.
——Protection of separately excited, against power failure (Edward Masterson), 236.
——Radio interference from direct-current, eliminating (George R. Conklin), *495.
——Speed, operating at increased (Nicholas J. Weiss), (John Coan), (Lee F. Dann), (C. Otto von Dannenberg), 136.
Grease (see Lubrication and Oil).
Grinder:
——Heavy, use of ball bearings on (G. R. Hanks), 237.
——Pedestal built by arc welding, *240.
——Shaft, straightening emery, *40.
——Surface, use of silent chain drive on (Donald A. Hampson), *437.
Grounds, recommended practices in installing and testing, *409.
Gun for use in cold weather, power grease (William B. Cone), *38.

H

Hamilton Manufacturing Company's plant, controlling maintenance costs in (Thomas W. Suddard), *45.
Handling materials (see also Conveyors, Cranes, Hoists, Trucks, etc):
——Acids spell safety, new methods of handling, *584.
——Conditions that limit production, overcome (editorial comment), 377.
——Electrical power instead of man power for, apply (editorial comment), 29.
——Elevators recast factory methods, chain (Edward J. Tournier), *558.
——Maintenance supplies in the Simmons Company plant (M. J. Schmitt), *502.
——Motors, bench truck for transporting or repairing (Donald A. Hampson), *543.
——Oil and grease lubricants (Frank E. Gooding), *113, editorial comment, 131.
——Problems, solving (D. B. Kift), *397.
——Steel chips by high air velocity, conveying (R. J. Collins), *20.
——Tomorrow's demands, consider (editorial comment), 490.
——Truck for shop use, construction of low (Henry Simon), 531.
Hangers (see Shafts).
Heating, electric (see also Oven):
——A.I.&S.E.E. committee report (George H. Schaeffer), 317.
——Lumber with electric heat, drying, 387.
——Oil, preheating fuel, *187.
——Requirements for heating the cold corner, how to determine the (C. A. Booth), *555.
——Steel mills, in (Arthur J. Whitcomb), *255.
——Unit heaters in industrial plants, applications of (Frank E. Gooding), *349, correction, *460.
——Units protected when blower belt breaks (D. W. Haire), *295.
——Water, electric heater lowers cost of heating, 538.
Hoists (see also Handling materials):
——Overtravel of, limit switch to prevent (Charles A. Peterson), *236.
——Trouble encountered while repairing ammonia purifier (A. L. Bingham), 386.
Hubbard Steel Foundry Company's machine shop, lighting (James Thomson), *17.

I

Idlers (see under Belts).
Incandescent lamps (see Lamps).
"Industrial Engineer":
——Changes its name to "Industrial Engineering," 426.
——Contest, winners of prize, *66.
"Industrial Engineering":
——Industrial Engineer changed to, 426.
——Industry Illustrated consolidated with (James H. McGraw), 549.
"Industry Illustrated" consolidated with "Industrial Engineering" (James H. McGraw), 549.
Industry, trends and developments in (editorial comment), 130.
Inspection and maintenance:
——Inspection:
Compensators, routine for, of starting (J. Elmer Housley), *173.
Cranes, routine for (D. W. Blakeslee), 238.
Routines cover out-of-the-way equipment, make (editorial comment), 130.
——Maintenance:
Costs, how we control our (Thomas W. Suddard), *45.
Drills, electric (Edwin L. Connell), *160.
Equipment, of (editorial comment), 84.
Lighting systems, cutting cost of (O. C. Callow), *66.
Mechanical equipment and buildings (Ira De Moss), *58.
Men required for, in a certain plant (Nathaniel W. Blanchard), 34.
Method into, putting (editorial comment), 286.
Radio—a new tool for the, department (editorial comment), 532.
Separate, from production (editorial comment), 226.
Service with, do not confuse (editorial comment), 490.
Small plant, in a (O. C. Callow), *272.
Studebaker Corporation's South Bend plants (John R. Sullivan), *216.
Supplies, handling (M. J. Schmitt), 502.
Welding in, electric arc (Robert E. Kinkead), *110.
Work is coming into its own (editorial comment), 178.
——Overhaul equipment, now is a good time to (editorial comment), 330.
——"Put it in and forget it" may be taken too literally (editorial comment), 29.
——Troubles, checking up and servicing electrical (C. H. Smith), 91.
——Trucks and tractors, storage battery (W. Landess), *63.
Installation (see Motor installation).
Installation of electrical equipment, planning an (Marin Phillips), *1, comment (Charles A. Peterson), 188.
Instruments (see Meters).
Insulation:
——Inferior grade of, cause of trouble (C. Otto von Dannenberg), 340.
——Oil, reclamation of insulating (Frank E. Gooding), *267.
International Economic Conference (editorial comment), 286.
Interpoles (see under Generators and Motor reconnection and repair).
Iron and Steel Electrical Engineers (see Association of).

J

Job, the:
——Emergency, do your men know what to do in an (editorial comment), 580.
——Fliers, take a tip from these, *581. (editorial comment), 85.
——Ideas, look outside your industry for (editorial comment), 85.
Prove the value of your (editorial comment), 178.
——Let good judgment govern procedure when experience is lacking (editorial comment), 28.
——Limits of the impossible, pushing back the (editorial comment), 427.
——Men who keep industry fit to fight, the (editorial comment), 501.
——Technically-trained man start in, where should the (editorial comment), 330.
——Ten years from now, what will you be doing (Practical Pete), 425.
——Work, when fewer men do more (editorial comment), 376.

L

Labor (see Job, the).
Ladders:
——Platform substituted for the shop, suspended (Donald A. Hampson), *404.
——Portable, precautions in the use of, 161.
——Wall, construction of rungs and safety ring for brick (Donald A. Hampson), *112.
Lamps (see also Lighting).
——Carbon-filament, have no place in your lighting system (editorial comment), 491.
——Life of, cause of short (A. L. Tuffly), (H. D. Fisher), (J. A. Bantau), (H. J. Achee), (Archie L. Forger), (William Koepernik), (E. Ogur), (E. J. Morrissey), *288.
——Select proper, using voltage records to, *234.
——Test, holder, handy 550-volt (James P. Marshall), *188.
Lighting (see also Lamps).
——Carbon-filament lamps have no place in your, system (editorial comment), 491.
——Cost of operating and maintaining, cutting (O. C. Callow), *66, comment (G. R. Kilburn), 174, answer by author, 175.
——Daylight illumination in industrial plants, cost of (M. Lockiesh and R. E. Mausk), *307.
——Fixtures:
Savings effected by changing (E. J. Elvish), 539.
Special, illuminating dark spots by (James P. Marshall), *186.
——Floodlight for temporary use portable (Charles A. Peterson), *188.
——Machine shop, system for (James Thomson), *17.
——Paint is an important factor in (editorial comment), 226.
——Revamping a, system during a production peak (Frank Millhof), *578.
——Steel mill, fifteen years of (Ward Harrison), *327.
——Steel mills (Arthur J. Whitcomb), *255.
——System help to cut production costs, let your (editorial comment), 427.
——Warning lights on crossing gates, controlling (Charles A. Peterson), *91.
Lineshaft (see Shafts).
Literature (see Books and Trade literature).
Lubricants (see Lubrication and Oil).
Lubrication (see also Oil).
——Bearings, ball and roller (E. J. Morrissey), 34, (Nathaniel W. Blanchard), (H. W. Holosworth), (W. E. Warner), 136.
——Bearings, oil grooves in bronze and babbitt (Grady H. Emerson), (H. D. Fisher), (H. J. Achee), (W. E. Warner), *428.
——Cranes, routine for (D. W. Blakeslee), 238.
——Feed solved problem, changing method of (F.E.G.), 142.
——Gun for outside use in cold weather, power grease (William B. Cone), *38.
——Insured by control devices and warning signal, 437.
——Motor trouble, scheduled oiling prevents (J. F. Morgan), *565.
——New equipment, show your men how to lubricate (editorial comment), 227.
——Oil hole location to new oilers, indicating (W. E. Warner), 295.
——Policies and practices, local conditions determine lubrication (W. E. Warner), 595.
——Power transmission equipment (Allen F. Brewer), *471.
——Reclamation of lubricating and insulating oils (Frank E. Gooding), *267.
——Storing and handling oil and grease lubricants (Frank E. Gooding), *113, editorial comments, 131.

*Indicates illustrated articles

409838

JAN 9 '28

M

Maintenance (see Inspection and).
Materials, handling (see Handling materials).
McGraw, James H., engineering and industry pay tribute to, *30.
Measurements (see Meters).
Meat packing (see Packing).
Men (see Job, the).
Meters:
——Ammeter:
Connection for, and relays (C. O. von Dannenberg), (A. Noeppel), (Ernest Dickinson), (Charles A. Peterson), (G. H. Wintersteen), (E. J. Elvish), *181.
Springs, soldering (G. H. Wintersteen), 137.
——Cutting, into circuit (Charles A. Peterson), *341.
——Departmental metering practice (J. Elmer Housley), *197.
——Graphic record interpretation of (H. D. Fisher), (J. W. Bantau), *536.
——Graphic, supported to overcome vibration (W. L. Stevens), *292.
——Three-phase power, will two single-phase meters measure (C. Otto von Dannenberg), (Grady H. Emerson), (James B. Holston), (E. A. Mills), *334.
Midwest Power Conference, report of, *119.
Mills:
——Cement:
Power-drive problems in a (A. C. Brown), *484.
Power in the (J. H. Lendi), *122.
——Paper, use of power in (V. D. Simons), 122.
——Steel:
Association of Iron and Steel Electrical Engineers (see under A).
Auxiliaries, control for (G. E. Stack), *261.
Drives, electric power (Arthur J. Whitcomb), *245.
Furnace doors electrically, operating (E. G. Peterson), *567.
Homestead Steel Works, electrical installations in new structural mills (C. A. Menk), 326.
Illumination, fifteen years of (Ward Harrison), *327.
Motors in, application of synchronous (Harry A. Winne), *325.
Power in, use of (Wilfred Sykes), 121.
Roll necks, application of tapered roller bearings on (Fred Waldorf), 321.
Rolling mills, anti-friction bearings on roll necks of (E. C. Gainsborg), 324.
Rolling mills, bearings for use in (C. J. Klein), 322.
Rolling mills, electric drives for (L. A. Umansky), *420.
Motor bearings (see Bearings).
Motor control:
——Arc-rupturing devices (H. D. James), *411.
——Compensator:
Dashpot in, cause of operating trouble, incorrectly assembled (Donald A. Hampson), *434.
Inspection of starting, routine for (J. Elmer Housley), *173.
Slip-ring motors be started by a can? (H. E. Stafford), (Lee F. Dann), (R. F. Emerson), (William McGuire), (Grady H. Emerson), (L. T. Johnson), 89.
——Controllers:
(H. D. James), *106.
Trouble with, due to improper assembly (Grady H. Emerson), *434.
——Functions of control in the operation of electric motors (H. D. James), *205.
——Furnace doors electrically, operating (E. G. Peterson), *567.
——Induction motors, check switch ratings carefully for double-squirrel-cage (editorial comment), 178.
——Conveyor clogs, to stop motor when (Charles A. Peterson), *234.
——Conveyor system magnetically controlled, complex (P. T. Van Bibber), *507.
——Obsolete equipment, replacing (W. J. Stock), (H. L. Van Valkenburg), (G. O. Wilms), (R. G. Widdows), 55.
——Relays, types and functions of overload (H. D. James), *527.
——Shearing pin, substitute for (L. E. Dunham), (Garson A. Reese), 290.
——Steel mills:
Auxiliaries, for (G. E. Stack), *261.
In (Arthur J. Whitcomb), *250.
——Time-limit control of loads having large inertia (B. W. Jones), *453.
Motor drive (see also Belts, Chains, Clutches, Couplings, Gears, etc.).
——Application is an individual problem, every (George L. Markland, Jr.), *452.
——Cement mill, problems in a (A. C. Brown), *484.
——Costs, helping to cut power transmission (editorial comment), 490.
——Equipment, trends in application of power drive (Frank E. Gooding), *445.
——Fans:
Exhaust, changing (E. Ogur), *142.
Flexible drive solves, operating problem, *93.
——Individual, give special machines increased operating flexibility (Donald A. Hampson), *94.
——Layouts, study effect of rearranging equipment on power drive (editorial comment), 533.
Motor drive (Continued):
——Problems:
Opinions are not the solution of (editorial comment), 179.
Study your power transmission (F. H. Willard), *465.
Tell us how you have solved your (editorial comment), 376.
——Shock or pulsating loads, methods of handling, *477.
——Short-center, transmitting power through, *461.
——Size of motor for group drives, maximum economical (B. W. Scott), 593.
——Steel mills, in (Arthur Whitcomb), *245.
——Variable-speed:
Operation problems, *466.
Transmission and variable-speed motor, operating comparison of (Paul J. Ziegelbaur), 143.
Transmission, worm speed reducers, chains and (Gordon Fox), *209.
Unit to select best operating speed, using a (E. G. H.), 595.
Motor installation and mounting:
——Base for, use of channel iron in making sliding (R. M. Thomas), *238.
——Base, improvised (Charles A. Peterson), *36.
——Electrical features of (Gordon Fox), *301.
——Overhead from special steel shapes, mounting power transmission equipment (P. L. Pryibil), *541.
——Overhead in saw-tooth construction, supporting motor (E. G. H.), *389.
Motor mounting (see Motor installation and).
Motor reconnection and repair:
——Armature:
Core bands, what causes armature to throw (C. W. Peden), (Axel T. Smith), (Albert E. Carpenter), (Robert B. Treat), (R. R. Schellenger), (Guy K. Mitchell), *230.
Double-commutator type, rewinding (Michael Reuter), *96.
Oven located out of doors, baking (R. C. Taylor), *95.
Slots raised speed of d.c. motor, opening (W. E. Warner), 192.
Stripping closed slot (A. C. Roe), 439.
Wedge tool simplifies rewinding, *309.
——Behavior of motor due to design, unusual (A. C. Roe), 239.
——Brushes:
Carbon, making emergency (Grady H. Emerson), *345.
Thickness of, minimum (Grady H. Emerson), 534.
——Coils:
A.C. motors with defective, may be kept in service, how (George Cropper), 96.
Damaged, in winding, cutting out (A. C. Roe), 494.
Field, drying out shunt (Arthur F. Hanly), 391.
Insulating, for semi-closed slot motors (Lee F. Dann), 95.
Mush, for a.c. and d.c. motor windings (A. C. Roe and D. H. Braymer), *21.
Short-throw, for chorded windings (A. C. Roe and D. H. Braymer), *126.
Short-type, and winding molds (A. C. Roe and D. H. Braymer), *369.
——Commutating poles on magnetic field, effect of (H. J. Achee), 382.
——Commutator:
Bars for industrial motors, selecting (Jesse M. Zimmerman), *168.
Grooves in, preventing the wearing of (Phil D. Comer), *391.
Reconditioning of direct-current (Grady H. Emerson), *596.
Segments, assembly of (Jesse M. Zimmerman), *561.
Segments for, cutting mica (A. C. Roe), *191.
Troubles often caused by neglect, simple (William L. Weber), 188.
V-ring, reinforcing mica (C. B. Keck), *145.
Wear out of round, why does this (W. E. Warner), (Grady H. Emerson), (C. Otto von Dannenberg), 495.
——D.c. motor troubles, causes and remedies for some (M. C. Cockshott), 187.
——D.c., tests to determine condition of medium-sized (E. Lindop), *438.
——Fan motor, heating of (Frank Harle), 231.
——Heating, wrong connections cause of (H. G. Millican), 435.
——Induction motors:
Speed of, changing (A. C. Roe), 90, (Lee F. Dann), Grady H. Emerson), (A. C. Roe), *233.
Wound rotor, changing speed of (Thomas Jordan), 40.
——Insulation:
Heat-resisting, for protecting windings against high temperatures (A. C. Roe and D. H. Braymer), *220.
Reinforced slot, prolongs motor life (H. J. Garrison), 344.
Semi-closed slot motors, for (A. C. Roe), *290.
Semi-closed slot motors, for (L. F. D.), (Grady H. Emerson), (H. J. Achee), (R. I. Frost), (C. McCollum), (J. M. Peterson), 384.
Tests, motor breakdown prevented by (W. E. Warner), 293.
——Interpoles, polarity of (J. W. Bantau), (J. M. Walsh), *291, (C. Otto von Dannenberg), (Henry Scheril), *432.
Motor reconnection and repair (Continued):
——Low voltage supply cause of puzzling motor trouble (Grady H. Emerson), 35.
——Oil on rotor causes of unusual trouble, heavy (Grady H. Emerson), 186.
——Overheating two motors due to overload (E. J. Morrissey), 341.
——Overloaded motor cool, auxiliary fan to keep, *340.
——Polarity tests for series, shunt and interpole field connections (C. D. Van Anden), 564.
——Poor workmanship and neglect cause shutdown of plant (Nathaniel W. Blanchard), 293.
——Portable equipment shows repairmen's time (Donald A. Hampson), *512.
——Production delays reduced by eliminating motor trouble (J. Elmer Housley), 71.
——Recording number of motors removed (J. Elmer Housley), *35.
——Repulsion-induction motors fail to start (Grady H. Emerson), 536.
——Rewinding (see Winding).
——Rotor bars to end rings, fastening (H. E. Stafford), (V. J. Winkle), *594.
——Shaft of motor cause bearings to overheat, does magnetized? (Charles Reichenbach), (E. J. Morrissey), (W. E. Warner), 339.
——Shop, layout of an up-to-date (H. E. Van Alstyne), *72.
——Single-phase motor for three-phase operation, changing (Grady H. Emerson), 594.
——Single-phase, testing fuses to prevent motors running (H. J. Achee), (Harold H. Steele), (E. J. Morrissey), *133.
——Single-phasing can be stopped (editorial comment), 130.
——Slot wedges saves time, round grooving tool for (Nicholas J. Weiss), 240.
——Speed of direct-current motor, changing (G. H. Wintersteen), (M. V. Miller), (H. J. Achee), 32.
——Squirrel-cage motor:
Speed of a, reduced (H. J. Achee), 391.
Trouble with (R. K. Hoke), (Henry Scheril), (F. H. Rooney), 430.
——Stators, removing wires from semi-closed-slot (A. C. Roe), (J. S. Murray), (H. J. Achee), (Nicholas J. Weiss), 433.
——Three-phase motor to run single-phase, rigid leads cause (E. J. Morrissey), *386.
——Troubles:
Chronic, there are definite reasons for (editorial comment), 226.
Unusual, cause of production loss (E. L. Way), 240.
——Tubing, making varnished (R. Buckett), 39.
——Two to three phase, changing a motor (A. C. Roe), 542.
——Water-soaked electrical equipment, reconditioning (A. C. Roe), 585.
——Winding:
Chord factor, determining (Charles F. Cameron), (Claude D. Martin), (Alex Brenner, Jr.), (H. Kaelin), 134.
Chorded, short-throw coils for (A. C. Roe and D. H. Braymer), *126.
Coil in, cutting out damaged (A. C. Roe), 494.
Delta and star-connected, difference between (Lee F. Dann), (E. J. Morrissey), (Claude D. Martin), *138, correction, 185.
Insulation for, protecting, heat-resisting (A. C. Roe and D. H. Braymer), *220.
Molds, construction details of short-type coils and (A. C. Roe and D. H. Braymer), *369.
Rewinding for different frequencies, factors in (M. V. Miller), 191.
Slip-ring motor, rotor winding of (A. C. Roe), (Samuel Carbat), (William McGuire), (G. H. Emerson), *336.
Star and delta connected, difference between (Lee F. Dann), (E. J. Morrissey), (Claude D. Martin), *138.
Tools that are easy to make, some handy (H. J. Achee), *192.
Motor repair (see Motor reconnection and repair).
Motor starters (see Motor control).
Motor testing (see Motor reconnection and repair and testing).
Motor troubles (see Motor reconnection and repair).
Motors (see also other Motor subjects).
——Frames, standardization of (editorial comment), 491.
——Fynn-Weichsel, characteristics of the (James B. Holston), (William McGuire), (W. R. Wolfe), (L. E. Dunham), (Percy Lamothe), (Lee F. Dann), *382.
——Obsolete, replacing (A. F. Davis), (A. G. Ahrens), (N. S. Yost), *54, (J. W. Corey), 125.
——Single-phase, testing fuses to prevent motors running (H. A. Maxfield), (R. V. Martyn), *33.
——Standardizing general-purpose (Clarence C. Collins), 36.
——Synchronous:
Industry, their place in (C. D. Kester), *457.
Steel mills, application in (Harry A. Winne), *325.

*Indicates illustrated articles

N

National Exposition of Power and Mechanical Engineering, 505.
National Safety Council's sixteenth Annual Safety Congress, 506.
New England flood, the (G. A. Van Brunt), *551, editorial comment, 580.
New equipment for plant operation and maintenance, *41, *97, *146, *193, *241, *296, *346, *392, *440, *496, *554, *597.
1927 (Practical Pete), *27, editorial comment, 28.

O

Obsolete equipment, replacing (G. A. Van Brunt), *51, 124.
Oil (see also Lubrication).
——Grooves in bronze and babbitt bearings (Grady H. Emerson), (H. D. Fisher), (H. J. Achee), (W. E. Warner), *429.
——Heavy, on rotor cause of unusual motor trouble (Grady H. Emerson), 186.
——Hole location indicated to new oilers (W. E. Warner), 295.
——Preheating fuel, by electricity, *187.
——Reclaiming lubricating and insulating (Frank E. Gooding), *267.
——Storage is costly, help-yourself (editorial comment), 131.
——Storing and handling (Frank E. Gooding), *113, editorial comment, 131.
Ovens, electric:
——Armature baking, located out of doors (R. C. Taylor), *95.
——Low-temperature, for industrial applications (Edwin Fleischmann), *276.
Oxy-acetylene (see under Welding).

P

Packing industry, power in the (C. H. Kane), *120.
Paint and painting:
——Lighting, an important factor in industrial (editorial comment), 226.
——Practices in industrial plants, painting (Frank E. Gooding), *78.
——Winter-time, requirements of (F. E. Gooding), *572.
Paper mills (see Mills).
Pete, Practical (see Authors' Index).
Pinion, location of motor (H. D. Fisher), (Guy H. Wintersteen), (A. Fiess), 132, (E. H. Laabs), (C. E. Schirmer), *537.
Pipes, thawing frozen water (R. W. Buckett), 34.
Plant, the:
——Engineering in pictures, *582.
——Maintenance in Studebaker Corporation's South Bend factories (Ira De Moss), *58.
——Service departments, check up on the location of your (editorial comment), 426.
Potentiometer to supply power for signal systems (Leo S. Loomie), *139.
Power drives (see Motor drives).
Power factor:
——Improve plant, loading synchronous motor to (Nicholas Cook), (J. Y. Shirley), (C. Otto von Dannenberg), *593.
——Raise our, how high should I? (James B. Holston), *9.
——Transformers feeding a resistance load of (Guy H. Wintersteen), 185.
Power question, where does your plant stand in regard to the (editorial comment), 28.
Power transmission (see Belts, Chains, Clutches, Couplings, Gears, Motor drive, etc.).
Power Transmission Association offers prize for emblem, 196.
Practical Pete (see Authors' index).
Press, draining static electricity from color printing (E. H. Laabs), *92.
Printing presses (see Presses).
Production, capitalizing the service to (editorial comment), 533.
Prosperity, long-time guarantees of (Edward J. Mehren), *523.
Protection, motor (see Motor control).
Pulleys:
——Diameter influence on power transmitted by leather belt drives (Roy C. Moore), *357.
——Fiber, refacing surface of (Donald A. Hampson), 342.
——Large diameter, on motor (H. D. Fisher), (H. S. Ramsay), (W. J. Lees), 86, (E. H. Laabs), 182.
——Loose, drives, oilless bearings on (Donald A. Hampson), 37.
——Wear due to slip of dusty belt, short center drive prevents, *595.
——Wear from abrasive dust on belts decreased, 295.
Purchasing (see Buying).

Q

Questions asked and answered by readers, *31, *86, *132, *180, *228, *288, *332 *378, *428, *492, *534, *592.

R

Radio:
——Interference from d.c. generator, eliminating (George R. Conklin), *495.
——Maintenance department, a new tool for the (editorial comment), 532.
Reactors, effects of overvoltage on contactor coils reduced by using (E. J. Morrissey), 35.
Records:
——Belt speed, chart for determining, *294.
——Charts and log sheets, keeping (E. J. Morrissey), *539.
——Equipment, system used in a large steel foundry (James Thomson), *415.
Records (Continued):
——Fire and watch service (J. A. Kaupel), *569.
——Lamps, using voltage records to select proper, *234.
——Maintenance costs, how we control our (Thomas W. Suddard), *45.
——Maintenance of electrical equipment in a small plant, organization and routine for (O. C. Callow), *272.
——Motors removed, recording number of (J. Elmer Housley), *35.
——Repair shop, of (H. E. Van Alstyne), *72.
——Service, let equipment write its history in (editorial comment), 131.
——Troubles, checking up and servicing electrical (C. H. Smith), 91.
——Value of your equipment in terms of the service it renders, measure the (editorial comment), 29.
——Wire, chart for finding physical properties of copper (C. F. Cameron), *139.
Refrigerator, operation of electric (Garson A. Reese), (Archie L. Forger), *87, (Phil D. Comer), (Frederick Krug), *334.
Relays:
——Connection for ammeter and (C. O. von Dannenberg), (A. Noeppel), (Ernest Dickinson), (Charles A. Peterson), (G. H. Wintersteen), (E. J. Elvish), *182.
——Overload protection to meet service demands, changing (H. Banholzer), 434.
——Overload, types and functions of (H. D. James), *527.
Repairs (see Motor reconnection and repair).
Replacing obsolete equipment (G. A. Van Brunt), *51, editorial comments, 84, 85, 124.
Respiration, artificial (see Safety).
Rewinding (see Motor reconnection and repair).
Rheostat for testing fields of d.c. motors and generators (J. M. Walsh), 145.
Rolling mills (see Mills, steel).
Roof that show location of leaks, markings on (Donald A. Hampson), 176.
Rope wire, measuring size of, *172.
Rotors (see Motor reconnection and repair).

S

Safety:
——Accidents, contributing causes of industrial (G. E. Kimball), 368.
——Acids, new methods of handling, *584.
——Bearings may prevent a fire in your plant, proper attention to (editorial comment), 84.
——Congress of National Safety Congress, 506.
——Cranes:
Operators, rules for the guidance of, 424.
Overhead, elimination of hazards in the operation of (C. E. Sankey), *283.
——Danger signs, legibility of color combinations used on, 222.
——Dust explosions, factors that influence origin and extent of, 19.
——Education must supplement safeguards (editorial comment), 331.
——Guard rail, constructing steel (A. F. Davis), *538.
——High-tension equipment, accident elimination in operation of (T. E. Hughes), 321.
——High-voltage hazards in industrial substations, prevention of (Walter C. Wagner), *525.
——Ladders:
Brick wall, construction of rungs and safety ring for (Donald A. Hampson), *112.
Portable, precautions in the use of, 161.
——Lock on pedal-operated machine (Charles A. Peterson), *538.
——Power, safe practices in handling high-tension (A. N. Cartwright), *320.
——Respiration, teach your men the prone pressure method of artificial (editorial comment), 179.
——Safeguard for all hazards, the best (editorial comment), 85.
——Switches:
Blades, fiber guard to prevent arcing between (Philip N. Emigh), *36.
Knife, converted from enclosed to safety type (S. H. Samuels), *40.
Screwdriver for use in close quarters (David Fliegelman), *96.
Service to production, capitalizing the (editorial comment), 532.
Shafts and shafting:
——Alignment of, checking the (Donald A. Hampson), *180.
——Countershaft to allow easy adjustment, mounting (Henry Simon), *342.
——Driving, by two motors (Guy H. Wintersteen), (N. G. Willen), (John J. Lynch), 594.
——Emergency bracket for mounting, on pit wall (Maurice C. Cockshott), *343.
——Hangers:
Ball bearing, give over 10-yr. life in flour mill (A. G. Beckman), 93.
Bearings, installing ball or roller (Donald A. Hampson), 237.
——Right-angle, testing alignment of (E. J. Morrissey), (H. D. Fisher), (R. B. Turner), (E. N. Dillard), (W. F. Schaphorst), *380.
——Scraper for cleaning oil and dust from (H. Moore), *540.
——Speed of lineshaft, effect of doubling (E. L. Way), (W. E. Warner), (E. J. Morrissey), 228.
Shafts and shafting (Continued):
——Supporting double row of, from building column (Donald A. Hampson), *189.
——Two from one motor, driving, *37.
Shelves for shop purposes, handy (E. J. Morrissey), *542.
Shops (see Motor reconnection and repair and Plants).
Signals:
——Crossing gates, controlling warning lights on (Charles A. Peterson), *91.
——Danger signs, legibility of color combinations used on, 222.
——Lubrication insured by control devices and warning, 437.
——Potentiometer to supply power for systems (Leo S. Loomie), *139.
Simmons Company plant, handling maintenance supplies in the (M. J. Schmitt), *502.
Smithsonian Institution's exhibit on steam engines, 568.
Soldering springs in ammeters (G. H. Wintersteen), 137.
Speed control (see Motor control, Motor reconnection and repair and Speed reducers).
Speed reducers:
——Application of gears and, on motor drives (Gordon Fox), *162.
——Emergency, built from auto steering gear (W. L. Stevens), 294.
——Limitations, some of their inherent (C. H. Grill), *401.
——Worm, chains and variable-speed transmissions (Gordon Fox), *209.
Speeds, standardization of machine (editorial comment), 227.
Spray density, one way to obtain constant, 159.
Standardization:
——Machine speeds will simplify operation, of (editorial comment), 227.
——Motor frames, of electric (editorial comment), 491.
——Motors, general-purpose (Clarence C. Collins), 36.
Standards:
——Gears are now in sight, for industrial (editorial comment), 376.
——Wrench stamping, engineering committee adopts simplified, 587.
Starters (see Motor control).
Static electricity from color printing press, draining (E. H. Laabs), *92.
Stator (see Motor reconnection and repair).
Steam engines, Smithsonian Institution's exhibit of, 568.
Steel Engineers (see Association of Iron and).
Steel mills (see Mills, steel).
Steel sheets from ingots, making thin (editorial comment), 427.
Stewart-Warner Speedometer Corporation's fire and watch service (J. A. Kaupel), *569.
Storage batteries (see Batteries).
Studebaker Corporation's South Bend plants, (Ira De Moss), *58, (John R. Sullivan), *216.
Subscription swindler gets 18 months in jail, *531.
Substations:
——Hazards in industrial, prevention of high-voltage (Walter C. Wagner), *525.
——Isolated, improves operating conditions in coal mine (J. S. Murray), 387.
Switchboard (see also Switches):
——Panel, disintegration of studs due to defective slate (W. E. Warner), 387.
——Truck-type, operating advantages of (F. M. Billhimer), *354.
Switches and switching:
——Emergency, lamp socket as (C. V. Hull), *539.
——Knife:
Blades, fiber guard to prevent arcing between (Philip N. Emigh), *36.
Converting, from enclosed to safety type (S. H. Samuels), *40.
——Limit, to prevent overtravel of hoist (Charles A. Peterson), *236.
——Magnetic, in control of complex conveyor system (P. T. Van Bibber), *507.
——Safety, one emergency application of enclosed (W. T. Stevens), *341.
——Time, use of (Frederick Krug), 89 (Nathaniel W. Blanchard), (W. E. Warner), (G. H. Wintersteen), 185.

T

Tank, repairing roof (Nathaniel W. Blanchard), 185.
Taps, tool for removing broken (G. A. Luers), *95.
Testing and tests:
——D. C. voltage for, reducing (C. Otto von Dannenberg), *239.
——Fields of d.c. motors and generators, rheostat for (J. M. Walsh), 145.
——Fuses to prevent motors running single-phase (H. J. Achee), (Harold H. Steele), (E. J. Morrissey), *133, (H. A. Maxfield), (R. V. Martyn), *34.
——Lamp holder, handy 550-volt (James P. Marshall), *188.
——Motor loads, using test receptacles in checking (Lee F. Dann), 141.
——Panel:
Appliance (Garson A. Reese), *439.
Giving choice of several voltages (Nathaniel W. Blanchard), *39.
Wiring and construction details of handy (E. J. Morrissey), *345.
——Polarity, for series, shunt and interpole field connections (C. D. Van Anden), 564.
——Transformers, determining condition of (Edwin W. Lindop), 293.
——Varnishes, insulating (V. A. Partz), 390.

*Indicates illustrated articles

Tools, electric (see also Drills and Grinders).
——Cords for portable, protection of (Francis A. Westbrook), *366.
Tools, non-electric:
——Grooving, for slot wedge saves time, sound (Nicholas J. Weiss), 240.
——Pulley, to reface surface of fiber (Donald A. Hampson), 342.
——Taps, for removing broken (G. A. Luers), *95.
——Wedge, simplifies rewinding armatures, *309.
——Winding, that are easy to make (H. J. Achee), *192.
——Wrenches, increasing grip of open-end (G. A. Luers), 516.
Tractors (see Trucks).
Trade literature you should know about, 44, 100, 148, 196, 244, 300, 348, 396, 444, 500, 548, 600.
Transformers:
——Auto-, building (T. A. Brenner), (Albert E. Carpenter), *232.
——Choice, characteristics govern (David R. Dalzell), *513.
——Condition of, simple tests for determining (Edwin W. Lindop), 292.
——Current, emergency lighting from (C. Otto von Dannenberg), (Guy H. Wintersteen), (A. C. Barker), 536.
——Fuses blowing on, cause of (C. Otto von Dannenberg), 90, (H. S. Ramsay), (W. E. Warner), (A. C. Barker), 184, (H. J. Achee), (C. Otto von Dannenberg), *494.
——Power factor of, feeding a resistance local (Guy H. Wintersteen), 185.
Transportation (see Handling materials, Trucks, etc.).
Transmission of power (see Belts, Chains, Clutches, Couplings, Gears, Motor drive, etc.).
Tripp, General Guy E., death of (editorial comment), 330.
Trucks, electric industrial:
——Inspection and maintenance routine for, and tractors (W. Landess), *63.
Trucks, now-electric:
——Bench, for transporting or repairing motors (Donald A. Hampson), *543.
Tubing (see under Motor reconnection and repair).

V

Varnishes:
——Insulating, give it a chance (editorial comment), 84.
——Testing insulating, specifications for (V. A. Partz), 390.
Vanished tubing (see Tubing under Motor reconnection and repair).
Vehicles (see Trucks).
Voltage, reducing d.c. (A. Fiess), (F. J. H. Krause), *431.
Voltmeter (see under Meters).

W

Watch service, supervision over fire and (J. A. Kaupel), *569.
Water-soaked electrical equipment, reconditioning (A. C. Roe), 585.
Water wheel casing by arc welding, repairing, *141.
Welding:
——Abrasion, use of welding in resurfacing wearing parts to resist, 400.
——Arc:
Maintenance work, in (Robert E. Kinkead), *110.
To keep equipment in service (J. S. Murray), *281, editorial comment, 286.
Water wheel casing by, repairing, *141.
What have you done with (Practical Pete), 177.
Welding (Continued):
——Castings replaced with welded steel parts, broken (Robert E. Kinkead), *344.
——Cutting cast iron with oxy-acetylene torch, *314.
——Process, solution of a (L. E. Everett), 313, comment (J. F. Lincoln), 404.
——Reinforcing welded joints to increase strength (G. A. Luers), 591.
——Truss member uses less metal, new welded, 579.
Wilson & Co., Union Stock Yards (Thomas C. Hayes), *149.
Winding, motor (see Motor reconnection).
Wire (see also Cable and Wiring).
——A. W. G. sizes, relations between (Charles F. Cameron), 91.
——Connector, cross-over (James P. Marshall), *144.
——Copper, chart for finding physical properties of (C. F. Cameron), *139.
——Groupings of, in conduit for two-phase system (H. S. Ramsay), (C. Otto von Dannenberg), (Ernest Dickinson), (A. C. Barker), (D. W. Blakeslee), (Alex Brenner, Jr.), *88.
——Socketing, cable, *511.
——Tools, protection of cords for portable electric (Francis A. Westbrook), *366.
Wiring (See also Wire).
——Motor installations, for (Gordon Fox), *360.
——Test panel, handy (E. J. Morrissey), *345.
——Trouble in conduit, locating (Albert J. Fiess), (Nathaniel W. Blanchard), (John J. Lynch), *338.
Workbench with minimum interruption, repairing, 176.
Worm gears (see under Gears).
Wrenches:
——Open-end, increasing grip of (G. A. Luers), 516.
——Stamping, engineering committee adopts simplified, 587.

AUTHORS' INDEX

A

ACHEE, H. J. Blowing of fuses on transformer bank, *494.
——Cause of short life of lamps, 289.
——Changing speed of direct-current motor, 32.
——Effect of commutating poles on magnetic field, 382.
——Insulation for semi-closed slot motors, 385.
——Locating grounded coil in a.c. generator, 292.
——Oil grooves in bronze and babbitt bearings, *429.
——Operating generators in parallel, *229.
——Reduced speed of a squirrel-cage motor, 391.
——Removing wires from semi-closed-slot motors, 433.
——Testing fuses to prevent motors running single-phase, 133.
——Trouble with storage battery charging generator, 136.
——Winding tools that are easy to make, *192.
Acker, G. H. Worm reduction units for power transmission, *6.
Adamson, C. H. Variable-speed operation problem, *469.
Ahrens, A. G. Replacing obsolete motors, 55.
Alford, J. T. How should this blower be driven? 332.
Ammann, Frank C. Trouble in setting circuit breakers, *493.
Anselm, Al. Providing fire protection for an industrial plant, *405.

B

BANHOLZER, H. Changing overload protection to meet service demands, 434.
Bantau, John W. Advantages of three-phase, four-wire system, 379.
——Cause of short life of lamps, 288.
——Interpretation of graphic meter record, 536.
——Polarity of interpoles, *291.
Bardrof, F. E. Handling shock or pulsating loads, 478.
Barker, A. C. Cause of fuses blowing on transformers, 184.
——Emergency lighting from current transformer, 537.
——Grouping of wires in conduit for two-phase system, 88.
Beckman, A. G. Ball bearing hangers give over 10-yr. life in flow mill, 93.
Beneze, Leo E. Damaged feeders replaced without interception to production, 235.
Billhimer, F. M. Operating advantages of truck-type switchboards, *354.
Bingham, A. L. Hoist trouble encountered while repairing ammonia purifier, 386.
——Improving operation of byproducts coke plant, *69.
Black, E. J. Replacing rubber belts, 57.
Blakeslee, D. W. Grouping of wires in conduit for two-phase system, 88.
——Routine for lubrication and inspection of cranes, 238.
——Substitute for crane collector bars, *34.
Blanchard, Nathaniel W. Formation of white incrustation on brick, 494.
——How many men are required for maintenance in this plant?, 34.
——Locating trouble in conduit wiring, 338.
Blanchard, N. W. (Continued):
——Lubricating ball and roller bearings, 136.
——Poor workmanship and neglect cause shutdown of plant, 293.
——Repairing roof tank, 185.
——Supporting trolley wire for monorail crane, *235.
——Test panel giving choice of several voltages, *39.
——Use of time switches, 185.
Booth, C. A. How to determine the requirements for heating the cold corner, *555.
Boyce, W. H. Layout of heavy bus structures, *256.
Braymer, D. H. (see also A. C. Roe).
Brenner, Alex., Jr. Determining chord factor, 135.
——Grouping of wires in conduit for two-phase system, 89.
Brenner, T. A. Building auto-transformer, *231.
Brewer, Allen F. Lubrication of power transmission equipment, *471.
Brown, A. C. Power-drive problems in a cement mill, *484.
Brown, C. E. (see Frank E. Gooding).
Buckett, R. Making varnished tubing, 39.
——Thawing frozen water pipes, 34.
Burr, W. H. Report of A. I. & S. G. E. electrical development committee, 319.

C

CALLOW, O. C. Cutting cost of operating and maintaining lighting systems, *66, comment (G. R. Kilbourn), 174, answer by author, 175.
——Installing anti-friction bearings in sleeve-bearing motors, 432.
——Organization and routine for maintenance of electrical equipment in a small plant, *272.
Cameron, C. F. Chart for finding physical properties of copper wire, *139.
——Determining chord factor, 134.
——How to use relations between A.W.G. wire sizes, 91.
Carbat, Samuel. Rotor winding of slip-ring motor, 336.
Carpenter, Albert E. Building auto-transformer, *232.
——What causes armature to throw core bands?, *230.
Carroll, H. M. Solving bearing troubles, 489.
Cartwright, A. N. Safe practices in handling high-tension power, *320.
Coan, John. Will this generator operate satisfactorily at increased speed?, 135.
Cockshott, M. C. Causes and remedies for some d.c. motor troubles, 187.
——Emergency bracket for mounting lineshaft on pit wall, *343.
Collins, Clarence C. Standardizing general-purpose motors, 36.
Collins, R. J. Conveying steel chips by high air velocity, *20.
Comer, Phil. D. Operation of electric refrigerator, *334.
——Preventing the wearing of grooves in commutator, *391.
Cone, William B. Power grease gun for outside use in cold weather, *38.
Conklin, George R. Eliminating radio interference from d.c. generator, *495.
Connell, Edwin L. Use of electric drills in maintenance and repair work, *160.
Conner, C. F. Rubber transmission belting, *12.
Cook, Nicholas. Loading synchronous motor to improve plant power factor, *593.
Corey, J. W. Replacing obsolete equipment, 125.
Corwin, C. D. Handling replacement of equipment, 52.
Cramer, Frank W. An analysis of the motor bearing problem, 323, comment (J. S. Murray), 388.
Cropper, George. How a.c. motors with defective coils may be kept in service, 96.

D

D., L. F. Insulation for semi-closed slot motors, 384.
Dalzell, David R. Characteristics govern transformer choice, *513.
Dann, Lee F. Can slip-ring motors be started by a compensator?, 89.
——Changing speed of induction motor, 233.
——Characteristics of Fynn-Weichsel motor, 383.
——Difference between star and delta-connected motor windings, 138.
——Insulating coils for semi-closed slot motors, 95.
——Trouble from cable overheating, 137.
——Using test receptacles in checking motor loads, 141.
——Will this generator operate satisfactorily at increased speed?, 135.
Davis, A. F. Constructing steel guard rail, *538.
——Replacing obsolete motors, *54.
De Moss, Ira. Maintenance of mechanical equipment and building, *58.
De Rabot, J. L. Handling shock or pulsating loads, *479.
——Short-center drives, *463.
Dickinson, Ernest. Connection for ammeter and relays, *181.
——Grouping of wires in conduit for two-phase system, *88.
Diehl, R. P. Substitute for crane collector bars, 34.
Dillard, E. N. Testing alignment of right angle shafts, 380.
Dunham, L. E. Characteristics of Fynn-Weichsel motor, 383.
——Substitute for shearing pins, 290.

E

ELVISH, E. J. Advantages of three-phase, four-wire system, 380.
——Charging storage batteries from exciter, 535.
——Connection for ammeter and relays, *182.
——Savings effected by changing electric light fixtures, 539.
——Trouble in setting circuit breakers, *492.
Emerson, Grady H. Belt required for certain drive, 31.
——Can slip-ring motors be started by a compensator?, 90.
——Changing single-phase motor for three-phase operation, 594.
——Changing speed of induction motor, *233.
——Disadvantage of supplying several departments from one feeder, 341.
——Heavy oil on motor cause of unusual motor trouble, 186.
——Insulation for semi-closed slot motors, 384.
——Life of bearings increased by individual fit, 542.

*Indicates illustrated articles

Emerson, G. H. (Continued):
——Low voltage supply cause of motor trouble, 35.
——Making carbon brushes in emergency, *345.
——Minimum thickness of brushes, 534.
——Oil groves in bronze and babbitt bearings, 428.
——Reconditioning of direct-current commutators, *596.
——Repulsion-induction motors fail to start, 536.
——Rotor winding of slip-ring motor, 337.
——Trouble with controller due to improper assembly, *434.
——What is wrong with this exciter?, *183.
——Why does this commutator wear out of round?, 495.
——Will two single-phase meters measure three-phase power?, *333.
Emerson, R. F. A.c. and d.c. motors for crane operation, *315.
——Can slip-ring motors be started by a compensator?, 89.
——Effect of altitude on capacity of generators, *337.
Emigh, Philip N. Fiber guard to prevent arcing between switch blades, *36.
——Replacing worn collector rings, 144.

F

FIESS, ALBERT J. Locating trouble in conduit wiring, *338.
——Location of motor pinion, 133.
——Reducing d.c. voltage, *431.
Fisher, H. D. Cause of short life of lamps, *289.
——Formation of white incrustation on brick, 494.
——How should this blower be driven?, 332.
——Interpretation of graphic meter record, *536.
——Location of motor pinion, 132.
——Oil grooves in bronze and babbitt bearings, *429.
——Replacing obsolete equipment, 124.
——Testing alignment of right angle shafts, *380.
——Using large diameter pulley on motor, 86.
Fleischmann, Edwin. Low-temperature electric ovens for industrial applications, *276.
Fliegelman, David. Screwdriver for use in close quarters, *96.
Forger, Archie L. Belt required for certain drive, 32.
——Cause of short life of lamps, *289.
——Operation of electric refrigerator, 87.
Fox, Gordon. Electrical features of motor installations, *301.
——Gears and speed reducers on motor drives, *162, comment (J. C. Roantree), 388.
——Use of belts on motor drives, *101.
——Wiring for motor installations, *360.
——Worm speed reducers, chains and variable-speed transmissions, *209.
Francis, D. R. Variable-speed operation problem, *467.
Frost, R. I. Insulation for semi-closed slot motors, 385.

G

G., F. E. Changing method of feed solved lubrication problem, 142.
Gainsborg, E. C. Anti-friction bearings on roll necks of rolling mills, 324.
Garrison, H. J. Reinforced slot insulation prolongs motor life, 344.
Gooding, Frank E. Applications of unit heaters in industrial plants, *349.
——Methods of storing and handling oil and grease lubricants, *113, editorial comment, 131.
——Painting practices in industrial plants, *78.
——Reclamation of lubricating and insulating oils, *267.
——Trends in application of power drive equipment, *445.
——Winter-time painting, *572.
Gooding, Frank E., and C. E. Brown. Power distribution in a large machine shop, *520.
Grill, C. H. Speed reducers, *401.

H

HAIRE, D. W. Protecting heater units when blower belt breaks, *295.
H., E. G. Supporting motor overhead in sawtooth construction, *389.
——Using a valuable-speed unit to select best operating speed, 595.
Hamilton, K. D.
——Handling replacement of equipment, 53.
——Short-center drives, 462.
Hampson, Donald A. Babbitting in bearing seats for ball or roller bearings, *436.
——Bench truck for transporting or repairing motors, *543.
——Checking the alignment of lineshafts, *180.
——Construction of rungs and safety ring for ladder on brick wall, *112.
——Familiarity with care of bearings in emergency prevented breakdown, 294.
——Handling shock or pulsating loads, *478.
——Improperly bored bearing causes trouble, 93.
——Incorrectly assembled dashpot in compensator cause of operating trouble, *434.
——Individual drives give special machines increased operating flexibility *94.
——Installing ball or roller hanger bearings, 237.
——Markings on roof that show location of leaks, 176.
——Oilless bearings on loose-pulley drives, 37.
——Portable equipment saves repairmen's time, *512.
Hampson, D. A. (Continued):
——Military noisy gears, 143.
——Refacing surface of fiber pulley, 342.
——Roller chain used on quarter-turn drive, 540.
——Substituting suspended platform for the shop ladder, *404.
——Supporting double row of shafts from building column, *189.
——Use of silent chain drive on surface grinder, *437.
Hanks, G. R. Use of ball bearings on heavy grinding machine, 236.
Hanly, Arthur F., Method of drying out shunt field coils, 391.
Hanson, J. Anti-friction bearings in flour mill, 37.
Harle, Frank Heating of fan motor, 231.
Harrison, Ward. Fifteen years of steel mill illumination, *327.
Haste, Stanley. Handling shock or pulsating loads, *480.
——Short-center drives, *464.
Hathaway, Charles. Belt required for certain drive, 32.
Hayes, Thomas C. Changing a distribution system from d.c. to a.c. service, *149.
Hertzler, G. D. Handling shock or pulsating loads, *478.
Hoke, R. K., Trouble with squirrel-cage motor, 430.
Holdsworth, H. W. Lubricating ball and roller bearings, 136.
Holston, James B. Characteristics of Fynn-Weichsel motor, *382.
——How high should I raise our power factor? *9.
——Will two single-phase meters measure three-phase power? *334.
Housley, J. Elmer. Departmental metering practice, *197.
——Handling replacement of equipment, 53.
——Production delays reduced by eliminating motor trouble, 71.
——Recording number of motors removed, *35.
——Routine for inspection of starting compensators, *173.
Hughes, T. E. Accident elimination in operation of high-tension equipment, 321.
Hull, C. V. Lamp socket as emergency switch, *539.

J

James, H. D. Arc-rupturing devices, *411.
——Controllers for electric motors, *106.
——Functions of control in operation of electric motors, *205.
——Types and functions of overhead relays, *527.
Johnson, L. T. Can slip-ring motors be started by a compensator?, 90.
Johnson, V. E. Charging storage batteries from exciter, 535.
Jones, B. W. Time-limit control of loads having large inertia, *453.
Jones, R. F. Horizontal quarter-turn belt drives, *155.
Jordan, Thomas. Changing speed of wound rotor induction motor, 40.

K

KAELIN, H. Determining chord factor, 135.
Kane, C. H. Power in the packing industry, *120.
Kass, Irving. Formation of white incrustation on brick, 494.
Kaupel, J. A. Fire and watch service, *569.
Keck, C. B. Reinforcing mica V-ring, *145.
Kester, C. D. The place of the synchronous motor in industry, *457.
Kift, D. B. Material handling problems, *397.
Kilbourn, G. R. Cutting cost of operating and maintaining lighting system, 174.
Kimball, G. E. Contributing causes of industrial accidents, 368.
Kinkead, Robert E. Electric arc welding in maintenance work, *110.
——Replacing Broken castings with welded steel parts, *344.
Klein, C. J. Bearings for use in rolling mills, 322.
Koepernik, William. Cause of short life of lamps, 289.
Krause, F. J. H. Reducing d.c. voltage, 431.
Krug, Frederick. Operating generators in parallel, 229.
——Operation of electric refrigerator, 335.
——Size of alternator required for industrial plant, 232.
——Use of time switches, 89.

L

LAABS, E. H. Draining static electricity from color printing press, *92.
——Location of motor pinion, *537.
——Using large diameter pulley on motor, 182.
Lamothe, Percy. Characteristics of Fynn-Weichsel motor, 383.
——How should this blower be driven?, 333.
Landess, W. Inspection and maintenance of storage battery trucks and tractors, *63.
Lane, Martin G. Effect of altitude on capacity of generators, 337.
Lees, W. J. Using large diameter pulley on motor, 87.
Lendi, J. H. Power in the cement mill, *122.
Lincoln, J. F. Selection of a welding process, 404.
Lindop, Edwin W. Determining condition of transformers, 292.
——Tests to determine condition of medium-sized d.c. motors, *438.
Loomie, Leo S. Use of potentiometer to supply power for signal systems, *139.
Luckiesh, M. and R. E. Mausk. Cost of daylight illumination in industrial plants, *307.
Luers, G. A. Emergency use of oversized cable clamp, 410.
——Increasing grip of open-end wrenches, 516.
——Reinforcing welded joints to increase strength, 591.
——Tool for removing broken taps, *95.
Lynch, John J. Driving lineshaft by two motors, 594.
——Locating trouble in conduit wiring, 339.

M

M., E. J. Simple mistakes that resulted in failure, 387.
Markland, George L., Jr. Even power drive application is an individual problem, *452.
Marland, J. A. Short-center drives, *462.
Marshall, James P. Cross-over connector, *144.
——Handy 550-volt test lamp holder, *188.
——Illuminating dark spots by special fixture units, *186.
——Locating blown fuses on panel board, *92.
Martin, Claude D. Determining chord factor, 134.
——Difference between star and delta-connected motor windings, *138, correction, 185.
——What is wrong with this exciter?, 183.
Martyn, R. V. Testing fuses to prevent motors running single-phase, 33.
Masterson, Edward. Protection of separately excited generators against power failure, 236.
Mausk, R. E. (see M. Luckiesh).
Maxfield, H. A. Testing fuses to prevent motors running single-phase, *33.
Mayhew, Gordon S. What is wrong with this exciter?, 184.
McCollum, C. Insulation for semi-closed slot motors, 385.
McGowan, A. A. Solving bearing troubles, *482.
McGraw, James H. A bigger and better service to our old and new friends, 549.
McGuire, William. Can slip-ring motors be started by a compensator?, 89.
——Characteristics of Fynn-Weichsel motor, 382.
——Rotor winding of slip-ring motor, 336.
Mehren, Edward J. Long-time guarantees of prosperity, *523.
Menk, C. A. Electrical installations in new structural mills, Homestead Steel Works, 326.
Merrill, Joseph J. Power in the food industry, 123.
Miller, M. V. Changing speed of direct-current motor, 32.
——Factors in rewinding motors in different frequencies, 191.
——What is wrong with this exciter?, 184.
Millhof, Frank. Revamping the lighting system during a production peak, *578.
Millican, H. G. Generator overload relieved by idle exciter, 538.
——Wrong connections cause of motor heating, 435.
Mills, E. A. Will two single-phase meters measure three-phase power?, *334.
Mitchell, Guy K. What causes armature to throw core bands?, 231.
Moore, H. Scraper for cleaning oil and dust from shafts, *540.
Moore, Roy C. Fixed and flexible idlers on leather belt drives, *310.
——Handling shock or pulsating loads, 480.
——Influence of pulley diameter on power transmitted by leather belt drives, *357.
——Proper center distances for leather belt drives, *201.
——Speed and power—their relation in leather belt drives, *509.
Morgan, J. F. Charging storage batteries from exciter, 535.
——Scheduled oiling prevents motor trouble, *565.
Morrissey, E. J. Cause of short life of lamps, 290.
——Difference between star and delta-connected motor windings, *138.
——Does magnetized shaft of motor cause bearings to overheat?, 339.
——Effect of doubling speed of lineshaft, 228.
——Effects of overvoltage on contactor coils reduced by using reactors, 35.
——Handy shelves for shop purposes, *542.
——How should this blower be driven?, 333.
——Industrial equipment advertising, 225.
——Keeping charts and log sheets, *539.
——Lubricating ball and roller bearings, 34.
——Overheating of two motors due to overload, 341.
——Rigid leads cause three-phase motor to run single-phase, *386.
——Testing alignment of right angle shafts, *380.
——Testing fuses to prevent motors running single-phase, *134.
——Trouble from cable overheating, 137.
——Trouble in setting circuit breakers, 492.
——What is wrong with this exciter?, 183.
——Wiring and construction details of handy test panel, *345.
Moss, Earl C. Substituting a long-center chain drive for bevel gears and shafts, *343.
Mulrooney, W. E. Replacing obsolete equipment, 53.
Mulvaine, E. A. Handling replacement of equipment, 52.
Murray, J. S. Anti-friction and slave-type bearings on motors, 388.
——Electric arc welding to keep equipment in service, *281, editorial comment, 286.
——Isolated substation improves operating conditions in coal mine, 386.

*Indicates illustrated articles

Murray, J. S. (Continued):
——Removing wires from semi-closed-slot motors, 433.
——Replacing obsolete equipment, 54.

N

NEEPER, W. B. Abuse of belt drives on high-inertia loads, 456.
Noeppel, A. Connection for ammeter and relays, *181.

O

O'DONNELL, D. F. Automatic charging station for storage battery trucks, *235.
Ogur, E. Cause of short life of lamps, *289.
——Changing method of driving exhaust fan solved motor trouble, *142.

P

P., C. A. How to care for a blow torch, *439.
Partz, V. A. Specifications for testing insulating varnishes, 390.
Pease, E. I. Belt required for certain drive, 31.
Pedrick, D. W. Eliminating belt slippage on coal breaker drive, 480.
Peden, C. W. What causes armature to throw core bands, *230.
Peterson, Charles A. Connection for ammeter and relays, *182.
——Constructing improvised motor base, *36.
——Controlling warning lights on crossing gates, *91.
——Cutting meter into circuit, *341.
——Emergency repair of defective field coil, 439.
——Handy oil well cover permits easy access to bearing, *144.
——Inexpensive and durable fuse puller, *293.
——Limit switch to prevent overtravel of hoist, *236.
——Making end connection for flexible conduit, *240.
——Planning distribution system, 188.
——Portable floodlight for temporary use, *188.
——Portable gage for determining depth of water in wells, *435.
——Safety lock on pedal-operated machine, *538.
——Simple control to stop motor when conveyor clogs, *234.
——Wooden case for protecting a pocket compass, 543.
Peterson, E. G. Operating furnace doors electrically, *567.
Peterson, J. M. Changing speed of electric drill, 431.
——Installation for semi-closed slot motors, 385.
Phillips, Marin. Planning an installation of electrical equipment, *1. comment (Charles A. Peterson), 188.
Practical Pete. Attend the Iron and Steel Convention by proxy, if you cannot be there in person, 285.
——Construction changes under difficulties, *129.
——Industrial equipment advertising, 225.
——In this issue you may find the solution of your problems, 83.
——Oversights that cost money, 375.
——The year 1927, p. *27.
——What have you done with electric arc welding?, 177.
——What will you be doing ten years from now?, 425.
Pryibil, P. L. Mounting power transmission equipment overhead from special steel shapes, *541.

R

RAMSEY, H. S. Cause of fuses blowing on transformers, 184.
——Changing speed of electric drill, 431.
——Grouping of wires in conduit for two-phase system, 88.
——Using large diameter pulley on motor, 86.
Reese, Garson A. Appliance test panel, *439.
——Operation of electric refrigerator, *87.
——Substitute for shearing pins, 291.
Reeves, R. F. Variable speed operation problems, *469.
Reichenbach, Charles. Does magnetized shaft of motor cause bearings to overheat?, 339.
Retter, Carl. Replacing obsolete equipment, 125.
Reuter, Michael. Rewinding double-commutator type armatures, *96.
Reynolds, H. R. Sowing bearing troubles, 483.
Rhoads, J. Edgar. Handling shock or pulsating loads, *480.
——Using two idlers to increase arc of contact, *456.
Roantree, T. C. Application of gears and speed reducers on motor drives, 388.
Roe, A. C. Best kind of insulation for semi-closed slot of motors, *290.
——Changing speed of induction motor, 90, 233.
——Cutting mica segments for commutators, *191.
——Cutting out damaged coil in windings, 494.
——Factors involved in changing a motor from two to three phase, 542.
——Reconditioning water-soaked electrical equipment, 585.
——Removing wires from semi-closed-slot motors, 433.
——Rotor winding of slip-ring motor, *336.
——Stripping closed slot armature, 439.
——Unusual behaviour of motor due to design, 239.
Roe, A. C., and D. H. Braymer. Construction details of short-type coils and winding molds, *369.
Roe, A. C., and D. H. Braymer (Continued):
——Heat-resisting insulation for protecting windings, *220.
——Mush coils for a.c. and d.c. motor windings, *21.
——Short-throw coils for chorded windings, *126.
Rogers, R. H. Variable-speed operation problem, *470.
Rooney, F. H. Trouble with squirrel-cage motor, 430.
Roselle, C. W. Advantages of three-phase, four-wire system, 380.

S

SALMONSEN, R. Short-center drives, 461.
Samuels, S. H. Converting knife switches from enclosed to safety type, *40.
Sankey, C. E. Elimination of hazards in the operation of overhead cranes, *283.
Schaeffer, George H. Report of A. I. & S. G. E. electric heat committee, 317.
Schaphorst, W. F. Testing alignment of right angle shafts, *381.
Schellenger, R. R. Replacing obsolete equipment, 125.
——What causes armature to throw core bands?, 231.
Scheril, Henry. Polarity of interpoles, 432.
——Trouble with squirrel-cage motor, 430.
Schirmer, C. E. Location of motor pinion, 537.
——Substitute for crane collector bars, 34.
Schmitt, M. J. Handling maintenance in the Simmons Company plant, *502.
Scott, B. W. Importance of skin effect in overheating of cables, 292.
——Maximum economical size of motor for group drives, 593.
Seeger, E. W. Variable speed operation problem, *468.
Shirley, J. Y. Loading synchronous motor to improve plant power factor, 593.
Simon, Henry. Construction of low truck for shop use, 531.
——Mounting countershaft to allow easy adjustment, *342.
Simons, V. D. Use of power in paper mills, 122.
Smith, Axel T. What causes armature to throw core bands?, 230.
Smith, C. H. Checking up and servicing electrical troubles, 91.
Stack, G. E. Control for steel mill auxiliaries, *261.
Stafford, H. E. Can slip-ring motors be started by a compensator?, *89.
——Fastening rotor bars to end rings, 594.
——Handling replacement of equipment, 52.
——Short-center drives, *463.
——Solving bearing troubles, 482.
Stevens, W. L. Emergency speed reducer built from auto steering gear, 294.
——Supporting graphic meters to overcome vibration, *292.
Stevens, W. T. One emergency application of enclosed safety switches, *341.
Steele, Harold H. Testing fuses to prevent motors running single-phase, 133.
Stock, W. J. Replacing control equipment, 55.
Streeter, Claude O. Replacing leather belts, 57.
Suddard, Thomas W. How we control our maintenance costs, *45.
Sullivan, John R. Maintenance of mechanical equipment and buildings, *216.
Sykes, Wilfred. Use of power in steel mills, 121.

T

TATNALL, R. R. Belt required for certain drive, 31.
Taylor, R. C. Armature baking oven located out of doors, *95.
Thomas, R. M. Bushing method of lengthening anchor bolts, *543.
——Use of channel iron in making sliding base for motor, *238.
Thomson, James. Equipment record system used in a large steel foundry, *415.
——Lighting system for large machine shop, *17.
Treat, Robert B. What causes armature to throw core bands, 230.
Tuffly, A. L. Cause of short life of lamps, 288.
Turner, R. B. Testing alignment of right angle shafts, *381.
Tournier, Edward J. Chain elevators recast factory methods, *558.
——Floor to floor conveyors, *517.
Turville, Horace. Advantages of three-phase, four-wire system, *379.
——Charging storage batteries from exciter, 535.
——Operating generators in parallel, *229.

U

UMANSKY, L. A. Electric drives for rolling mills, *420.

V

VAN ALSTYNE, H. E. Layout of an up-to-date electric repair shop, *72.
Van Anden, C. D. Polarity tests for series, shunt and interpole field connections, 564.
Van Bibber, P. T. How a complex conveyor system was magnetically controlled, *507.
Van Brunt, G. A. Replacing obsolete equipment, *51.
——What a flood means to the plant engineer, *551, editorial comment, 580.
Van Valkenburg, H. L. Replacing control equipment, 56.
Vining, R. N. Replacing obsolete equipment, 124.
von Dannenberg, C. Otto. Advantages of three-phase, four-wire system, *378.
——Blowing of fuses on transformer bank, *494.
——Cause of fuses blowing on transformers, 90.
——Charging storage batteries from exciter, *535.
——Connection for ammeter and relays, 181.
——Grouping of wires in conduit for two-phase system, 88.
——Emergency lighting from current transformer, 537.
——Inferior grade of insulation cause of trouble, 340.
——Loading synchronous motor to improve power factor, 593.
——Polarity of interpoles, *432.
——Reducing d.c. voltage for testing purposes, *239.
——Trouble from cable overheating, 136.
——Why does this commutator wear out of round?, 495.
——Will this generator operate satisfactorily at increased speed?, 135.
——Will two single-phase meters measure three-phase power?, *333.

W

WAGNER, CARL A. Rewinding small headlight generator armatures, 344.
Wagner, Walter C. Prevention of high-voltage hazards in industrial substations, *525.
Waldorf, Fred. Application of tapered roller bearings on roll necks, *321.
Walsh, J. M. Checking condition of elevator cables, 493.
——Polarity of interpoles, 291.
——Rheostate for testing fields of d.c. motors and generators, 145.
Warner, W. E. Cause of fuses blowing on transformers, 184.
——Disintegration of studs due to defective slate panel, 387.
——Does magnetized shaft of motor cause bearings to overheat?, 339.
——Effect of altitude on capacity of generators, 337.
——Effect of doubling speed of lineshaft, 228.
——Indicating location of oil holes to new oilers, 295.
——Local conditions determine lubrication policies and practices, 595.
——Lubricating ball and roller bearings, 136.
——Motor breakdown prevented by insulation tests, 293.
——Oil grooves in bronze and babbitt bearings, *429.
——Opening armature slots raised speed of d.c. motor, 192.
——Use of time switches, 185.
——Using white metal for rebabbitting bearings, 540.
——Why does this commutator wear out of round?, 495.
Way, E. L. Effect of doubling speed of lineshaft, 228.
——Uunsual motor trouble cause of production loss, 240.
Weber, H. F. Short-center drive, *462.
Weber, William L. Simple commutation troubles often caused by neglect, 188.
Weckstein, S. M. Application of roller bearings to conveyors, *575.
Weiss, Nicholas J. Eliminating trouble with rotary converter due to poor contacts, 39.
——Removing wires from semi-closed-slot motors, 433.
——Round grooving tool for slot wedges saves time, 240.
——Will this generator operate satisfactorily at increased speed?, 135.
West, A. K. Solving bearing troubles, *482.
Westbrook, Francis A. Protection of cords for portable electric tools, *366.
Whitcomb, Arthur J. Steel mill electric power drives, *245.
Widdows, R. G. Replacing control equipment, 56.
Willard, F. H. Study your power transmission problems, *465.
Willen, N. G. Driving limeshaft by two motors, 594.
Wilms, G. O. Replacing control equipment, 56.
Winne, Harry A. Application of synchronous motors in steel mills, *325.
Winkle, V. J. Fastening rotor bars to end rings, *594.
Wintersteen, G. H. Changing speed of direct-current motor, 32.
——Connection for ammeter and relays, *182.
——Driving lineshaft by two motors, 594.
——Emergency lighting from current transformer, 537.
——Location of motor pinion, 133.
——Power factor of transformers feeding a resistance load, 185.
——Soldering springs in ammeters, 137.
——Use of time switches, 185.
Wolfe, W. R. Characteristics of Fynn-Weichsel motor, 383.
Wood, F. C. How should this blower be driven?, 333.
Wray, A. B. Limitations of silent chain drives, *589.

Y

YOST, N. S. Replacing obsolete motors, 55.

Z

ZIEGELBAUR, PAUL J. Operating comparison of variable-speed transmission and variable-speed motor, 143.
Zimmerman, Jesse M. Assembly of commutator segments, *561.
——Selecting commutator bars for industrial motors, *168.

*Indicates illustrated articles